



Sounding Bob Level Meter

Are you facing this kind of trouble?

... You consider to apply non-contact level measuring such as ultrasonic or radar model, but in the application, adhesion or dust happens and it will bother stable measurement...



Malfunction by dust



Malfunction by adhesion

Sounding Bob Level Meter, contact and mechanical model, will enable stable measurement !!



Condition	Non-contact Level Meter	Sounding Level Meter
Influence of measuring material's adhesion	Yes	No
Influence of dusts	Yes	No
Influence of measuring material's objective change	Yes	No
Necessity of initial adjustment	Yes	No

High reliability of mechanical model !

The actual surface can be correctly detected without any environmental influence !



KSL-T2
Standard



KSL-W2B
Standard



KSL-MT
Built-in CPU
Compact



KSL-T8
Built-in CPU



KSL-GT
Withstand pressure
explosion proof

Measuring tape or wire is selectable. Applicable to various size of silos (Max. measuring span 40m)
Wide range of specification is available according to the applications.